

## BUILDING SAFETY CERTIFICATE

No. 1173

Dated 10/04/2023

Certified that the existing building Holy Mary International School  
Bhoop Bhairo, Chandri Chowk, Papan Road, Sitamarhi  
 comprised of — basement(s) and Ground  
and one (upper floors) owned/occupied by  
Holy Mary International School, Bhoop Bhairo, Chandri  
Chowk, Papan Road, Sitamarhi (name of the Institution) have complied with the  
 Building safety requirements in accordance with National Building code Rules, and verified by  
 the officers concerned of Executive Engg. PWD on 10/04/2023 in the presence of  
Nitesh Kumar Jaisankar, Phulahi, Pawan, Muz (name and addresses of the  
 Manager/Secretary or his representative) and that the building/premises is fit for occupancy  
 upto classes I to X (X/ XII) with effect from 10/04/2023 for a period of  
One years in accordance with rule and subject to compliance of the specific  
 conditions as appended.

1. No addition and alteration be made in the existing Building.
2. At the staircases should be kept clear from any obstacle.
3. School management will acquire fire safety from fire department.
- 4.

Issued on 10/04/2023 at Sitamarhi PWD by

\* Strike out whichever is not applicable.

Signature with Seal: Amit  
10/04/23

Name: PWD, Sitamarhi

Designation: Executive Engineer

Name & Address of Department/ Office: PWD

(Assistant Engineer & above officer of concerned Govt. Department only)

कार्यपालक अभियंता  
 भवन प्रमंडल  
 सीतामढ़ी

Manager  
 Holy Mary International School  
 Bhoop Bhairo, Chandri Chowk, Papan Road  
 Sitamarhi- 843319

Principal  
 Holy Mary International School  
 Bhoop Bhairo, Chandri Chowk, Papan Road  
 Sitamarhi- 843319