

## FIRE SAFETY CERTIFICATE

No. 2714

Dated 15-12-2022

Certified that the Holy Mary International School comprised of basement(s) and 01 (upper floors) owned/ occupied by Holy Mary International School (name of the institution) have complied with the fire prevention and fire safety requirements in accordance with rule of State/ UT Fire Service Rules, and verified by the officers concerned of Fire Service on 15-12-2022 in the presence of Mr. Shri Kishor Roy and that the building/ premises is fit for occupancy upto classes X ( X / XII) With effect from 15-12-2022 for a period of 01 year in accordance with rule and subject to compliance of specific conditions as appended:-

1. All the fire safety Arrangements shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviations w.r.t. construction etc shall be verified by the concerned building sanctioning authority.

Issued on 15-12-2022 at Sitamarhi by

\*Strike out whichever is not applicable.

Signature with Seal: Lalan  
15/12/22

Name : Lalan Prasad Sinha

Designation : Fire Station Officer

Name & Address of Department/ Office: Sitamarhi

To

The Chairman

Holy Mary International School

Sitamarhi

अग्निशामालय पदाधिकारी  
सीतामढ़ी

## ENDORSEMENT

The No Objection Certificate issued by Fire Service stand cancelled and annulled due to  
(reasons to be recorded).

(Name and designation of the authorized signatory)

Lalan  
Manager  
Holy Mary International School  
Bhoop Bhairo, Chandri Chowk, Papan Road  
Sitamarhi- 843319

Lalan  
Principal  
Holy Mary International School  
Bhoop Bhairo, Chandri Chowk, Papan Road  
Sitamarhi- 843319